



### CHARACTERISTICS

- Remover
- For remains of cured PU foam.

### PACKING AND COLOURS

15 bottles of 500 ml/box - 48 boxes/pallet

### METHOD OF USE

#### Preparation

Before applying the product, preliminary tests should be carried out to determine that the surfaces, will not be affected by the remover.

#### Application

- First remove cured foam mechanically as much as possible.
- Then apply the remover on the remains of the foam, directly or by means of a cloth.
- In order to stop the removing effect, wash away with plenty of water.

### SAFETY

Safety data sheet available on request.

### LIMITATIONS

Can affect surfaces like varnish, paint and textile.

This technical data sheet replaces all previous editions. The data on this sheet have been compiled according to the last laboratory report. Technical characteristics can be changed or adapted. We are not responsible for any incomplete information. Before use, one needs to ensure that the product is suitable for his application. Therefore, tests are necessary. Our general conditions apply.